



Mr. & Mrs.

On 8/19/2019, Cities' Inspection Service, Inc. completed a partial home inspection of the property located at XXXXX,XXXXXX, Minnesota for you. Doug Hastings did all the fieldwork related to this project. Doug used the national home inspection protocol; the American Society of Home Inspectors (ASHI) Standards of Practice.

The method used for this inspection was visual. There was no destructive analysis or technical testing of any building component. The project excluded all environmental health hazards, such as concealed mold, mildew and fungal growth; and any insect and vermin infestations.

The purpose of this inspection was to observe the physical condition of the buildings major systems. The intent was to identify defects or conditions that adversely affected the structure; main electrical, plumbing and mechanical systems. This inspection pertains only to the below listed systems. This is not *a complete home inspection.* This report contains the results of the inspection.

Structure

Foundation: cinder block Floors: wood frame Walls: wood frame with wood shakes Roof: wood frame rafters with asphalt shingles

Electrical

Utility service: overhead 110/220 volt Main panel: 200 amp

Plumbing

Main water pipe: copper Water heater: 40 gallons Main waste pipes: cast iron Fuel: natural gas

Mechanical

Heating: forced air Cooling: central air conditioner

Definitions that are used:

Functional: component was performing its intended function; installation and condition were appropriate for age and use.

-	
K 7	٩
I X	1
V	J

()

Major Defect: component was <u>not</u> performing its intended function and requires repair or replacement.




Minor Defect: component deficiency was insufficient to be major defect; but it requires repair, normal maintenance, or a safety improvement.



Potential Concern: component is old, nonexistent, not visible, or not viewed operating.

Major System Inspection

Explanation of Problems






Water stained foundation




Water damaged wall behind shower



Verify transfer of warranty




Flat grade (west side)






Pitted slab / deteriorated blocks

<u>Electrical</u>






Plumbing







Sewer concern

Heating

System_____ heat exchanger _____ A.... not visible vent & flue_____ 🔘

Cooling

Condenser	_0
compressor	_0
refrigerant pipes_	\odot

Component ages (approximate years)

- ✓ siding_____79
- ✓ windows_____79
- ✓ roof shingles____5
- ✓ electrical panel 79
- ✓ water heater 21
- ✓ furnace_____22
- ✓ air conditioner 22

Probability of Failure

- ✓ structure___low
- ✓ electrical _____medium (double tapped breakers)
 - (water heater age)
- ✓ plumbing____high ✓ sewer____unknown (camera scope)
- ✓ heating ____high (age)
- ✓ cooling____high (age)