www.citiesinspection.com



September 1, 2019

Mr. and Mrs.

On 8/14/2019, Cities' Inspection Service, Inc. completed a home inspection of the property located at XXXXXXX, XXXXXXX, Minnesota for you. Doug Hastings did all the fieldwork related to this project. Doug used the national home inspection protocol; the American Society of Home Inspectors (ASHI) Standards of Practice.



The method used for this inspection was visual. There was no destructive analysis or technical testing of any building component. The project excluded all environmental health hazards, such as concealed mold, mildew and fungal growth; and any insect and vermin infestations.


The purpose of this inspection was to observe the physical condition of this building. The intent was to identify defects or conditions that adversely affected the structure and its components. This report contains the results of the inspection. Definitions that are used:

- **Functional:** component was performing its intended function; installation and condition were appropriate for age and use.
- 🚫 Ma
 - **Major Defect:** component was <u>not</u> performing its intended function and requires repair or replacement.
- **Minor Defect:** component deficiency was insufficient to be major defect; but it requires repair, normal maintenance, or a safety improvement.
- A **Potential Concern:** component is old, nonexistent, not visible, or not viewed operating.

Exterior

Description of Exterior

Building: 2 level townhouse	Garage: 1 car attached	Approx. age: 25 years
Wall covering: vinyl lap siding	Layers: 1	Approx. age: 25 years
Windows: slider	Glass: insulated	Approx. age: 25 years
Roof covering: asphalt composition shingles	Layers: 1	Approx. age: 5 years




Major Defect

• Minor Defect

A Potential Concern

Grounds Observations

Explanation of Problems





Settled concrete



Tipped fence

Exterior Observations

weather: fair

Wall surfaces

siding	⊗ loose bricks / loose siding / hole in siding / blocked vent
windows	⊗ leaking transom glass
doors	⊙ torn patio door screen / screen off track
overhangs	




Bowed brick





Loose brick veneer



Loose siding



Hole in siding




Blocked vent



Leaking glass

Roof surfaces

viewed: walked on roof



Probability of Moisture Intrusion

- ✓ grounds low
- ✓ walls___low
- ✓ roof low


Limitations to Exterior Observations

• Leaking insulated window and door glass air seals may not be visible.

Structure

Description of Structure

Foundation: concrete and grade slab	Insulation: none visible	
Floors: wood trusses	Insulation: fiberglass	Inches: 3
Walls: wood frame studs	Insulation: not visible	
Roof: wood truss rafters	Insulation: fiberglass	Inches: 12



🚫 Major Defect

Minor Defect


A Potential Concern


Structure Observations


Explanation of Problems

Foundation

crawl space viewed: none







- ✓ floors____low
- ✓ walls___low
- ✓ roof____low

Limitations to Structure Observations

- Foundation is 100% covered and condition not visible.
- Floors are 95% covered and condition not visible.
- Wall structure is 100% covered; wood decay and molds are not visible.

Electrical

Description of Electrical

Utility service: underground	Volts: 110/220
Panel size: 100 amps	Approx. age: 25 years
Main disconnect: circuit breaker	Service wires: aluminum
Branch circuits: circuit breakers	Distribution wires: copper
	 Functional Major Defect Minor Defect Potential Concern
Electrical Observations	Explanation of Problems
Utility service	
Main panel panel location: north garage wall	
size	
condition	
wiring	
Outlets and fixtures	
exterior 💽 inoperable pat	tio GFI
garage inoperable GFI	
mechanical room_ 🚫 extension cord jacuzzi tub wiring	
finished walls 🔬 not visible	
attic 📐 not visible	



Jacuzzi tub wiring

Detectors

smoke______ Old bedroom detectors CO______ Q.... no upper level hallway detector

Limitations to Electrical Observations

• None.

Plumbing

Description of Plumbing

Main visible water supply pipe: copper	Interior water pipes: copper
Water heater: natural gas 40 gallons	Approximate age: 25 years
Soil stack: plastic	Drain & vent pipes: plastic




Plumbing Observations

Explanation of Problems

Water pipes

main water shutoff valve located: near furnace




Limitations to Plumbing Observations


• Condition of underground sewer pipe is not visible.

Mechanical

Description of Mechanical



Short cycling



Air conditioner

 condenser______

 \u00eddetty dirty coil / short cycling compressor______

 \u00eddetty high cooling temperature interior coil______

 \u00eddetty not visible piping______

 \u00eddetty not visible \u00eddetty use visible \u00eddetty use visible wiring______

 \u00eddetty use visible \u00eddetty use visible \u00eddetty use visible \u00eddetty use visible \u00eddetty use visi

Probability of Failure

\checkmark	heating	high	(old)
1			7

✓ cooling___high (old)

Limitations to Mechanical Observations


• System heat exchanger is 100% inaccessible and condition is not visible.


Interior


Description of Interior

ML bedrooms: 0	UL bedrooms: 2 Baths: 2
	Functional
	8 Major Defect
	Minor Defect
	🖄 Potential Concern
Interior Observations	
	Explanation of Problems
Stairs	
main	(lacksquare
Kitchen	
wall, ceiling, floc	
door	
outlet and fixtur	
plumbing	
cabinet and top_	
Appliances	
refrigerator	\bigcirc disconnected or inoperable ice & water dispenser
stove	
dishwasher	
disposal	
	📐 not viewed operating
unvented fan	
Living and dining room	n
wall, ceiling, floc	-
-	or 🚫 leaking window glass
outlet and fixtur	
heat	
	🔬 gas off & not viewed operating
<u> </u>	

ML half bath







Loft

wall, ceiling, floor	
door	
outlet and fixture	
clothes washer	_ 🔆 no overflow tray / no emergency water shutoff
clothes dryer	
Hallway and entry	
wall, ceiling, floor	
outlet and fixture	
Probability of Moisture Intr	rusion
✓ ceiling low	

- ✓ walls___low✓ floor___low

Limitations to Interior Observations

• Kitchen and laundry appliances are tested using normal operating controls to activate the primary function only. Operating or confirming operation of all other controls and features are not part of the inspection.

Conclusions

🚫 Major Defects

Exterior

- ✓ Loose brick wall veneer.
- ✓ Leaking window glass air seals.

Electrical

- ✓ Inoperable upper bath GFCI outlet.
- ✓ Extension cord whirlpool tub pump outlet. This outlet is not dedicated to the pump.
- ✓ Old bedroom smoke detectors. No upper level hallway CO detector.

Mechanical

- ✓ Furnace and air conditioner are short cycling.
- ✓ Air conditioner cooling temperature is too high.

Interior

✓ Disconnected refrigerator ice and water dispenser.

• Minor Defects

Exterior

- ✓ Cracked & settled front patio slab.
- ✓ Tipped fence posts.
- ✓ Loose vinyl wall siding. Hole in siding. Blocked wall vent.
- ✓ Torn patio door screen. Screen off its track.

Plumbing

- ✓ Water heater thermostat set too high (scalding water).
- ✓ Hard water and no water softener.
- ✓ Low main level bath sink hot water pressure.
- ✓ No clothes washer overflow tray. No washer emergency water shutoff valve.

Mechanical

- ✓ Worn furnace draft fan bearings.
- ✓ Dirty air conditioner condenser coil.

A Potential Concerns

Old components; short useful life:

- ✓ Furnace (less than 2 years)
- ✓ Air conditioner (less than 2 years)
- ✓ Water heater (less than 1 year)
- ✓ Patio door glass air seals (anytime)

Not visible or limited view (not part of the inspection):

✓ Underground sewer pipe (below grade)

Not viewed operating (not part of inspection):

- ✓ Garage water spigot (blocked access)
- ✓ Fire sprinkler
- ✓ Fireplace (gas off)
- ✓ Microwave